

NIUSAT Status after Two Years in Orbit

NIUSAT has been received at Belarus Ground station (Europe) for the last five days. On 26th Apr 2020 they received the Rx for the whole 7 orbits. From the spectrum waterfall image it is observed that the satellite is transmitting at 5sec interval which indicates that NIUSAT satellite is in normal operation mode (Battery Charged above 7.1V) after two and half years in orbit.

